

HMK® R80 Stripper Stain Remover



Strips heavy wax coats, sealers, impregnators, paint, oil, grease, varnish, tar, cleaning films and other dried on dirt and stains.

For use on all natural and artificial stones, ceramic and porcelain tiled surfaces.

HMK® R80 is a ready to use solvent based stripper for removing old impregnators, sealers, wax treatments, paint, film built up from regular cleaning products, asphalt and bitumen, grease, oils and varnish from all natural and artificial stone surfaces, ceramic and porcelain tiled surfaces as well as terracotta and brick/ block paving. R80 loosens dried on dirt and coatings from surfaces, allowing for easy and effective removal. R80 can be used in a poultice. For internal and external use.

Instructions: Protect adjacent surfaces. If under floor heating exists, switch it off and allow the surface to cool. Apply a generous coat of R80 undiluted onto the dry surface using a stiff brush, scrubbing brush or suitable pad and leave for 5 to 15 minutes. Do not allow to dry. After 5 to 15 minutes, scrub the area again vigorously. Afterwards clean the area thoroughly with HMK® R55 Intensive Cleaner -acid free- diluted about 1:10 with clean water. Remove the dirty liquid and rinse the area again with clean water. If patches remain untreated after drying, repeat the treatment as necessary.

Note: Some coatings require several applications or may not allow for chemical stripping.

Important: Do not apply in direct sunlight. Do not apply on rubber, plastic, perspex, lacquered surfaces and solvent intolerant materials. If these areas are splashed, remove splashes and rinse thoroughly with clean water.

When using a wet vacuum we recommend that you add HMK® Z102 Defoamer to the water to regulate the amount of foam.

Coverage: About 5-10m²/litre.

Warning: Chemical product. Contains naphtha, petroleum product. Flammable. Keep away from heat and flame. Harmful or fatal if swallowed or inhaled. Ensure adequate ventilation during the application process. Avoid eye/skin contact and breathing vapour or mist. If exposed flush/wash with water and seek medical attention. Keep container closed and out of the reach of children. See Material Safety Data Sheet for more detailed information.

Packaging: 12 x 1 litre bottles/box; 4 x 5 litre cans/box; 2 x 10 litre cans/box.

Storage: Store in a cool place and keep lid tightly closed.

Testing: Always test the product in an inconspicuous area to evaluate suitability, coverage and performance. Do not use the product in temperatures below 12 and above 25°C.

Limitation of liability: The liability of HMK® Moeller Stonecare for defective products and any claims for damages whatsoever is limited to the purchase price of the products. HMK® Moeller Stonecare shall not be liable for any consequential damages. No other warranty or representation is made or implied.